TLF. +4529745678
Zinga Danmark info@zinga.dk
Www. zinga.dk

ZINGA vejledning og datablad.

Zinga kan bedst beskrives som flydende galvanisk enkomponent overfladebehandling.
Denne behandling er det tætteste der kommer på en oprindelige varmgalvanisering og med et minimum af spild.

Zink indhold i tørfilmen er **96 %**.

Zinga kan påføres på en ren og ru overflade. med pensel/rulle/handske eller sprøjtes på.





TLF. +4529745678
Zinga Danmark info@zinga.dk
Www. zinga.dk

Declaration of Performance of ZINGA® 2021

1. Unique Product Type Identification(s) :
   FILM GALVANIZING SYSTEM – ZINC METAL SYSTEM – GALVANIC PROTECTIVE COATING SYSTEM

2. Batch Number and Production Date : as indicated on each individual can or pail.

3. Properties :
   Volume solids : 58% ±2% Weight solids : 80% ±2% Flash point : 47°C
   VOC content : less than 200 g/kg Density : 2,67 kg/dm³ T° resistance : -40°C to 120°C
   Solvent : Aromatic hydrocarbon solvent. Does not contain xylene, toluene or heavy metals.

4. Use & characteristics : INDUSTRIAL ONSHORE & OFFSHORE – RETAIL DIY
   ZINGA® is a one component Film Galvanizing System containing 96% zinc (dust) in its dry film.
   It is a metallic coating and not a paint. The purity of the zinc used is so high that dry ZINGA® does not contain any toxic elements (99.995% pure atomized zinc powder).
   ZINGA® protects old, new & galvanised or metallized steel structures from rusting.
   ZINGA® is applicable on-site or in a workshop, by brush, roller or spray equipment.
   ZINGA® is environmentally friendly, non-toxic and has an unlimited shelf and a very long pot life (> 48h).
   ZINGA® is a reversible coating and has the unique feature to reload existing Zinganized, hot-dip or metallized structures.
   ZINGA® applied at 60µm DFT covers 3,62 m²/kg
   ZINGA® can be used in contact with potable drinking water
   ZINGA® is applicable in severe environments and weather conditions with up to 95% Relative Humidity.

5. Producer : ZINGAMETALL BV – Rozenstraat 4, B-9810 Eke, BELGIUM (www.zinga.eu)
   Registry & VAT number : BE 0421 689 088 – Nacebel code : 20300

6. Authorised Distributors : 110 independent ZINGA® Distributors worldwide (cfr. ZINGA® website)

7. External & Internal Quality and Production Control :
   - Annually by SGS independent consultants and by foreign national quality controllers.
   - ZINGAMETALL BV is ISO 9001-2015 and ISO 14001-2015 certified.
   - All the production batches of ZINGA® are quality controlled, are digitally recorded into a pdf document and a physical sample of 2 kg is kept in our warehouse for at least 15 years.

8. Technical Approvals and Tests : *(* not all approvals & test on ZINGA® are mentioned here!)*
   - C.O.T. (Netherlands) laboratory tests :
     ZINGA® single layer 120µm DFT as stand-alone system with the following theoretical resistance results, according the new ISO 12944 standard of 2018 :

Standard	Category	Typical exterior environment	Durability
ISO 12944-6 (2018)	C5 VERY HIGH	High humidity & aggressive industrial atmospheres, coastal areas with high salinity	More than 25 years
ISO 12944-9 (2018)	CX EXTREME	Offshore high salinity, extreme humidity & aggressive industrial (e.g. tropical)	15 to 25 years
ISO 12944-9 (2018)	Im4	Immersion in sea or brackish water	15 to 25 years

   - ZINGA® passed NORSOK M501 tests at 120 µm DFT as stand-alone system (Syst. 1 & 7A & 7B).
   - ZINGA® passed ASTM B-117 (Salt spray): ZINGA® 2 x 90 µm DFT - over 4200 hours passed (ISO 9227).
   - ZINGA® is resistant to MIC - Microbial Induced Corrosion & passed the test at ENDURES Laboratory (Netherlands).
   - ZINGA® electro-potential measurement by University of Ghent and BNF (UK) : average of -1110 mV
   - ZINGA® passed bend test by C.O.T. Laboratory (Netherlands): no cracks with cylindrical mandrel of 12mm (ISO 1519)
   - ZINGA® passed the NSF/ANSI/CAN 61 test (USA-CANADA) for use in potable water tanks.
   - ZINGA® tested for slip coefficient (ASTM A325) and 1,000 h for Creep Deformation test (ASTM A490) by KTA TATOR (USA) : slip coefficient 0.52

Signed by the Authorised Representative of ZINGAMETALL BV
Bruno SAVERYS - CEO
25 February 2021

Bvba ZINGAMETALL Sprl
Industriepark – Rozenstraat 4
B – 9810 EKE (Belgium)
Tel: +32(0)9 385 68 81
Fax: +32(0)9 385 58 69
Email: zingametall@zinga.be
www.zinga.eu

(Established according to the EU Regulation 305/2011/EU)

TLF. +4529745678
Zinga Danmark info@zinga.dk
Www. zinga.dk

Zinga i opløst tilstand / vådfilm.

Produktkomponenter	Zinkpulver Aromatiske kulbrinter Bindemiddel
vægtfylde	2,67 kg/dm³ (±0,06 kg/dm³)
Tørstof indhold	• 80% forhold til vægt (±2%) • 58% forhold til volume (±2%) i henhold til ASTM D2697
Produkt fortynder	Zingasolv
Flamme punkt	≥ 40°C - 60°C
Flygtige organiske forbindelser	474 g/L (EPA Method 24) (=178 g/kg) measured by SMI, Inc.

Tørfilm

Farve	Grå (farve kan skifte afhængig af omgivelser og miljø , nøjagtig som en galvanisering)
Glans	Mat
Zink indhold	96% i tørfilmen (±1%) i vægt, renhed af zink 99,995%. ZINGA giver fuld katodisk beskyttelse og lever op til ISO 3549. Renhed af zink er i henhold til ASTM A780 standarden
Særlige egenskaber	• modstandsdygtighed af tørfilm (temperatur og pH værdi) » Minimum: -40°C » Maximum: 120°C med en spidsbelastning på 150°C • pH modstandsdygtighed *nedsænket* / 5,5 pH - 9,5 pH. • pH modstandsdygtighed i atmosfære : 3,5 pH to 12,5 pH. • Meget høj UV modstandsdygtighed
Ikke giftigt	En tør overflade af ZINGA er ikke giftig. *Se AS/NSZ 4020*. (Godkendelse til brug i drikkevands beholdere i New Zealand)

Opbevaring

Holdbarhed i ubrudt emballage	Ubegrænset. Ved lang opbevaring, bør den rystes mindst hver 3.de år
Opbevaring	Opbevares tørt mellem 5°C and +25°C.
Brugstid	Forudsat ordentlig forsegling , indtil produktet er opbrugt.

Overflade klargøring

Forarbejde og klargøring, på ikke galvaniserede overflader	- det er bedst at rengøre stål med 140 bar med 80°C varmt vand. Efterfølgende blæses til en **sA 2,5** , ifølge standard ISO 8501-1:2007 eller til en renhed der opfylder SSPC-SP10 og NACE nr 2. - Det betyder at overfladen skal være fri fra rust, fedt, olie, maling, salte, glødeskaller og anden forurening, rengøres med ren trykluft. Se ISO 8502-3 (se engelske beskrivelse vedr. blæsning med vand) •
Overflade ruhed	• Det er anbefalet at påføre zinga på en overflade med en ruheds grad Medium G i overenstemmelse. Med ISO 8503-1:2012. • **Sikre at overfladen er rengjort før evt. sandblæsning** • **En sådan grad af overflade ruhed er ikke nødvendig når Zinga påføres en varmgalvaniseret eller metaliseret lag, eller en tidligere behandling med Zinga. *En ældre varmgalvanisering her en tilfredsstillende ruhed og kan efter rengøring påføres direkte.***
Maximum tid før påføring	Påfør ZINGA hurtigst muligt på den klargjorte overflade, før den bliver forurenet eller der forekommer korrosion, I modsat fald er det nødvendig at foretage ny rengøring .

TLF. +4529745678
Zinga Danmark info@zinga.dk
Www. zinga.dk

Omgivelse Forholdsregler Under Påføring

Omgivelses temperatur	• Minimum -15°C • Maximum 50°C
Relativ luftfugtighed	• Maximum 95% • påfør ikke på fugtig eller våd overflade
Overflade temperatur	• Minimum 3°C over dugpunkt • ingen synlig tilstedeværelse af vand eller is • Maximum 60°C
Produkt temperatur	Under påføring skal temperaturen af den flydende Zinga være mellem 5 and 25°C. En lavere eller højere temperatur vil kunne ses.

Påførings Instruktioner

Generelt

Påførings metode	ZINGA kan påføres en ren overflade. Med pensel, rulle, konventionel sprøjte eller Airless sprøjte
Udstikning	Det anbefales at udstikke hjørner, skarpe kanter, bolte og møtrikker før et jævnt lag påføres
Omrøring	ZINGA skal **mekanisk omrøres grundigt** for at opnå en homogen og ensartet væske før påføring Efter max 20 min. Skal processen gentages. Brug zingasolv til justering.
Rengøring	Før og efter brug af sprøjteudstyr, skylning med frisk Zingasolv. Pensler og ruller skal skylles med Zingasolv. **Brug aldrig sprit**

Påførsel Med Pensel Og/Eller Rulle

Fortynder	For optimalt brug, fortynd ZINGA med optil 5%, se tabel for fortynder
Første lag	For at opnå det bedste resultat bør første lag ikke påføres med rulle, men med med pensel. For at fylde fordybninger på den profilerede profil, (ikke nødvendig på ældet galvaniske overflade.
Type af pensel eller rulle	Anbefalet at bruge industriel rund pensel, Korthåret rulle (mohair)

Påførsel Med Traditionel Sprøjte

Fortynder	Op til 15% med Zingasolv (se tabel for fortynder) afhængig af dyse størrelse . Mængden af fortynder giver en glattere overflade,
Dysetryk	2 til 4 bar (konventionel sprøjte)
Dysestørrelse	1,8 til 2,2 mm
Krav til sprøjte udstyr	• Det anbefales at fjerne alle filtre fra malesprøjte for at forhindre blokader • Sprøjtepistol skal være med en kraftig nåleventil • Brug kortest mulige dyserør

Påføring Med Airless Spray

Fortynder	Op til 7 % med Zingasolv (se tabel for fortynder) afhængig af dyse størrelse . Mængden af fortynder giver en glattere overflade,
Dysetryk	150 bar
Dysestørrelse	0.017 - 0.031 inch

TLF. +4529745678
Zinga Danmark info@zinga.dk
Www. zinga.dk

Fortynding Af Zinga

	/Pensel eller rulle 5%	Konventionel sprøjte 15%	Airless sprøjte 7%
1 kg	0.05 kg / 0.06 L Zingasolv	0.15 kg / 0.17 L Zingasolv	0.07 kg / 0.08 L Zingasolv
2 kg	0.10 kg / 0.12 L Zingasolv	0.30 kg / 0.35 L Zingasolv	0.14 kg / 0.16 L Zingasolv
5 kg	0.25 kg / 0.30 L Zingasolv	0.75 kg / 0.90L Zingasolv	0.35 kg / 0.40 L Zingasolv
10 kg	0.50 kg / 0.60 L Zingasolv	1.5 kg / 1.70 L Zingasolv	0.70 kg / 0.80 L Zingasolv
25 kg	1.25 kg / 1.50 L Zingasolv	3.75 kg / 4.30 L Zingasolv	1.75 kg / 2 L Zingasolv

Rækkeevne Og Forbrug

Teoretisk dækkeevne	- ved 60 µm DFT: 3,62 m²/kg eller 9,67 m²/L - ved 120 µm DFT: 1,81 m²/kg eller 4,83 m²/L
Teoretisk forbrug	- ved 60 µm DFT: 0,28 kg/m² eller 0,10 L/m² - ved 120 µm DFT: 0,55 kg/m² eller 0,21 L/m²
Praktisk dækkeevne og forbrug	Afhængig af ruheds profil og påførings metode

Tørre Proces Og Overmaling

Tørre proces	Zinga tørrer gennem fordampning af fortynder, Tørring er påvirket af total WTF, og påvirkes af omgivelses temperatur og luftighed og materialets overflade temperatur.
Tørre tid	Ved 60 µm DFT på 20°C, i vel ventilerede omgivelser : » Støv tørt : 15-20 min. » overflade tørt : 30-45 min. » Tør ved tryk : 90 min. » Gennemtør : 24 timer
Overmaling med nyt lag af ZINGA	Påførsel med pensel: 1 time efter berøringstørt . Påførsel med sprøjte : 30 min, efter overfladetørt. Maksimal tid før overmaling afhænger at omgivelser, hvis der er gået så lang tid af zincsalte findes på overfladen, skal disse fjernes, det anbefales at lag nr 2 påføres samme dag.

Genopfriskning ZINGA	Ved hvert lag af ZINGA gøres de samlede lag til et sammenhængende og homogent lag. Som følge heraf bliver det samlede lagtrykkelse til en samlet katodisk beskyttelse . Se Zinga på gammel varmgalvanisering
Overmaling med kompatibel maling	ZINGA kan overmales på kompatible malinger, for at undgå blærer eller porehuller. (Eng. blistering or pinholes). (Noget som kan have negativ indflydelse på ZINGA) Anbefaler vi at påføre topcoat med en teknik af tåge/fuld coat teknik. Først påføres **tyndt kontinuerligt** lag som tillader afdampning, dette lag giver også en barriere som forhindrer zingacoatning i at blive opløst Tåge sprøjtning • Påfør tidligst 4 tim, (ved 20°C) efter at Zinga er berøringstør. • 15 til 30 µm DFT (**kontinuerligt lag**). • Fortynd i normalt forhold, ifølge teknisk datablad . Fuld coat/hel maling: • Påfør mindst 2 timer efter at tågesprøjtning er berøringstør • Specificeret lagtykkelse minus 15 til 30 µm DFT (af tågesprøjte laget). • Fortynd i normalt forhold, ifølge teknisk datablad .

TLF. +4529745678
Zinga Danmark info@zinga.dk
Www. zinga.dk

Måling Af Lagtykkelse

Vådfilm tykkelse	• Anbefaling i henhold til ISO 2808. • WFT af ZINGA skal måles med en vådfilmskam • Afhænger af fortyndings grad , tørfilmen af ZINGA kan beregnes udefra Vådfilm : DFT = WFT * (sbv/100) *SBV er opløsningsmiddel i forhold til volume* • Når Zinga bliver påført af flere omgange skal man huske at et tidligere påført lag vil blive opløst. • **Det er derfor det samlede lag der så måles (altså sum af lag 1 og lag 2)**
Tørfilm tykkelse	• Ifølge ISO 2808. • Tørfilmtykkelse (DFT) bør måles med magnetisk induktions måler. F.eks elcometer 456. • Påførsel af Zinga i 2 lag, Anbefales at første lag er tykkere end det sidste lag.
Antal af målinger	Ifølge ISO 19840
Korrektions værdier	• I henhold til ISO 19840, overflade profilen er defineret som 'medium'. Som følge heraf er **korrektionsværdien 25 µm** . • Korrektionsværdien skal fratrækkes de individuelle målinger.

Kriterier for måling	• I henhold til ISO 19840. • Gennemsnit af de individuelle tørfilm tykkelses målinger, skal være lig med, eller større end nominel tørfilm tykkelse ((NDFT). = **Nominel dry film thickness** • All individuelle tørfilm tykkelser skal være lig med eller over 80 % af (nominel tørfilmtykkelse) NDFT. • Individuelle mellem 80% af NDFT og 100 % NDFT betegnes som acceptabelt forudsat at det er mindre end 20 % af alle individuelle mål. • Alle individuelle målinger skal være lig med eller mindre end specificerede **maximale** lagtykkelse .

Anbefalet System

Zinga som unik System Stand-alene	• ZINGA bliver brugt som et stand-alone, • Påføres med maksimalt 2 lag, med en maksimal lagtykkelse på 150 µm (DFT). • ZINGA bør aldrig påføres en lagtykkelse der overstiger 250 µm. • Dette system kan stærkt anbefales pga. den **lette vedligeholdelse**. • Over tid vil Zinga laget aftage som enhver anden galvanisering, helt som alle andre katodiske • beskyttelser . • Man behøver ikke at fjerne noget af det gamle Zinga, kun rengøring er nødvendig . • Kun tørfilmen af det tilbageværende Zinga afgør om den skal udbedres .evt kun lokalt, • Dette system er testet til følgende • ZINGA 80 - 100 µm DFT: » **Iso 12944-6:** C4 High, C5 Medium • ZINGA 120 µm DFT: » **Iso 12944-6:** C5 Very High, CX, Im4 » **Norsok m-501:** syst. 7, syst. 1
Duplex system	• In a duplex system, ZINGA should be applied in **one single application**, preferably by spraying, to obtain a DFT of 60 with a maximum of 100 µm DFT. • Several duplex systems have been tested according ISO12944. Please consult a Zingametall representative or the Zingametall website (www.zinga.eu) for more information.
Duplex system	

OVERVIEW MAIN TEST REPORTS ON ZINGA

To view the actual reports, please contact a Zingametall representative.

GALVANIC PROTECTION

ISO 12944 - COT*

ISO 12944-6: Paints and varnishes -- Corrosion protection of steel structures by protective paint systems

The ISO 12944 standard is intended to assist engineers and corrosion experts in adopting best practice in corrosion protection of structural steel with coatings at new construction and repairs. ISO12944 is progressively superseding regional standards to become a truly global benchmark in corrosion control

Different ZINGA systems (see below) have been subjected to extensive testing such as water condensation test, neutral salt spray test, chemical resistance test and water immersion test. After a prescribed exposure test (depending on respresentative environment), the coating is assessed for adhesion, blistering, rusting, cracking and flaking.

Environments are classified according corrosivity from C1 to C5. Meaning:
- C1: Indoor, nutral atmosphere (classrooms, offices, ...)
- C2: Rural areas, low pollution (Rural buildings, traffic lights, ...)
- C3: Urban and industrial atmospheres, moderate sulphur dioxide levels, production areas with high humidity (City buildings, factories, sign posts, ...)
- C4: Industrial or coastal (with moderate salinity) zones (chemical factories, swimming pools, shipyards, ...)
- C5I: Industrial zones with high humidity and aggressive environment, continuous condensation and high pollution (heavy chemical factories, oil and gas facilities, ...)
- C5M: Coastal zones and marine zones with high salinity, continuous condensation and high pollution (Marine, offshore, estuaries, ...)

And three environments for structures in immersion:
- Im1: Clear, fresh or potable water
- Im2: Sea or brackish water (harbors with locks, jetties, offshore structures; make sure there is no stray current)
- Im3: Soil (underground storage, iron poles)

After exposure, the coating is evaluated as H(igh), M(edium) or L(ow); reflecting in a life expectancy of:
Low: Life expectancy less than 5 years
Medium: Life expectancy between 5 and 15 years
High: Life expectancy more than 15 years

Tested Zingametall sytems:

Systems with High Classification in C4 environment:
- ZINGA 2 x 60 µm DFT


Systems with High Classification in C5 environment:
- ZINGA 2 x 90 µm DFT
- ZINGA 1 x 60-80 µm DFT + Zingalufer 1 x 80 µm DFT
- ZINGA 1 x 60-80 µm DFT + Zingaceram HS 1 x 120 µm DFT
- ZINGA 1 x 60-80 µm DFT + Zingaceram HS 1 x 120 µm DFT + Zingaceram PU 1 x 60 µm DFT
- ZINGA 1 x 60-80 µm DFT + Zingaceram HS 1 x 120 µm DFT + Zingaceram EP 1 x 60 µm DFT

Systems with Medium Classification in Im2 and Im3:
- ZINGA 2 x 60 µm DFT
- ZINGA 2 x 90 µm DFT


Systems with High Classification (Life expectancy > 15 years) in Im2 and Im3:
- ZINGA 1 x 60-80 µm DFT + Zingatarfree 2 x 100 µm DFT



ZINGA 2 x 90 µm DFT after 720 h condensation (above) and 1440 h salt spray (under)



ZINGA + Zingaceram HS + Zingaceram EP after 720 h condensation (above) and 1440 h salt spray (under)



ZINGA + Zingaceram HS + Zingaceram PU after 720 h condensation (above) and 1440 h salt spray (under)


ASTM B117 / ISO 9227 (SALT SPRAY TESTING) - COT / NCKU

ASTM B117: Standard practice for operating salt spray (fog) apparatus


ISO 9227: Corrosion tests in artificial atmospheres -- Salt spray tests

ZINGA 120 µm DFT passed a 10.000 hours salt spray test (without scratch!) according ASTM B117 with 1% red rust on the surface.


ZINGA 180 µm DFT passed a 4200 hours salt spray test (with scratch, demanding higher galvanic protection) according ISO 9227 with 1-5% red rust on the surface.



ZINGA 2 x 90 µm DFT after 2000 h salt spray



ZINGA 2 x 90 µm DFT after 3000 h salt spray



ZINGA 2 x 90 µm DFT after 4000 h salt spray

NORSOK M-501 / ISO 20340 - COT

NORSOK M-501: Surface preparation and protective coating
ISO 20340: Paints and varnishes -- Performance requirements for protective paint systems for offshore and related structures

NORSOK M-501 is an industry standard for adequate surface preparation and use of coating materials, developed with the emergence of the Norwegian oil industry.
ISO 20340 deals with performance requirements for protective paint systems for offshore and related structures (i.e. those exposed to the offshore environment, as well as those immersed in sea or brackish water).

ZINGA has passed the 4200 hours seawater immersion test and the 4200 hours cyclic test without any formation of rust, blisters, cracks, flakes or cathodic disbondment. The pull-off adhesion test on ZINGA resulted in values of more than 7 MPa.

IMO MSC.215 (82) (BALLAST TANK TEST) - DNV*

IMO MSC.215 (82): performance standard for protective coatings for dedicated seawater ballast tanks in all types of ships and double-side skin spaces of bulk carriers

ZINGA was applied on blast-cleaned test panels that were placed in a ballast tank filled with sea water with wave movement and cyclic heating. Other test panels were placed in a condensation chamber.
No corrosion of the steel substrate could be demonstrated. Based on the results of the testing, ZINGA meets the requirements of a B3 classification - due to insufficient adhesion (but this poses no threat to ZINGA, whereas paints rely on this to perform). In the report is stated that ZINGA has a beneficial corrosion protective performance. For B1 classification, we refer to ZINGA BT.



ZINGA 2 x 60 µm DFT after 180 days in a condensation chamber (left) or a wave tank (right)


BS3900-F10 (CATHODIC DISBONDMENT TEST) - BODYCOTE*

BS3900-F10: Methods of test for paints. Determination of resistance to cathodic disbonding of coatings for use in marine environments

ZINGA applied at 60 and 100 µm DFT was exposed during 26 weeks at -1,0 volt. The results was no cathodic disbondment at all.

ELECTRO-POTENTIAL MEASUREMENTS - COT

The sample ZINGA has been applied on sandblasted steel test panels of the specified quality. The test panels were partially immersed in 1.5% NaCl electrolyte at 23°C.
After 24 h immersion, the electrical potential of the panels has been determined, using a Standard Silverchloride Electrode (Ag/AgCl) as reference Electrode. Reported averaged measurements have been corrected for electrode drift and translated to SCE values.
The panels coated with ZINGA, have an averaged potential of -1110 mV (SCE); compared to -682 mV of blanc steel. The current density remains positive during the entire test, which indicates cathodic protetion by the coating.



ZINGA IN COMPARISON WITH HDG

ELECTRO-POTENTIAL MEASUREMENTS - UGENT / BNF*

In 2009, The University of Ghent (prof. dr. Defrancq) conducted several electrochemical tests to compare the galvanic protection of ZINGA to the established protection of Hot-Dip Galvanising. it was demonstrated that the short circuit flow of equal layer thicknesses of ZINGA and HDG have equal maximal current for an equal amount of time.
Therefore it is concluded that the electrochemical background of galvanic protection in ZINGA is equal to HDG.

In 1992, the renown research association BNF, performed extensive electrochemical testing on ZINGA and HDG.
In the experiment, the open circuit voltage and galvanic current between ZINGA and bare steel were measured over a range of area ratios. These results were compared with those from identical tests in which the ZINGA was replaced by hot-dipped galvanised steel.
The corrosion rate of the ZINGA coated specimens after 7 days exposure was 0.035mm/year, roughly 113 of the corrosion rate of galvanised steel panels under similar conditions (0.1 l mm/year). In the tests where the ZINGA coated and galvanised panels were coupled to mild steel samples, the potential of the coupled electrodes always remained below -800mV SCE, which showed that both ZINGA and galvanised steel offer good galvanic protection to the steel.

ASTM B117/ISO 9227 (SALT SPRAY TESTING) - SABS*

In this test is demonstrated that the loss in weight of ZINGA is 1/10 of the loss in weight of hot-dip galvanising after a 400 hours salt spray test. The layer thickness of ZINGA diminishes because ZINGA is being consumed, contrary to a paint that will start to peel off after a certain period of time. This illustrates the fundamental difference between a paint and a galvanising system.





* BNF - British Non-Ferrous Metals Research Association (UK) / SABS - South African Bureau of Standards (South-Afrioa)

FIELD TEST - SERVICE MARITIME DE LA VENDÉE



Two buoys (one treated with ZINGA, the other one hot-dip galvanised) have floated in the Atlantic
Ocean for four years. After those four years, the buoy treated with ZINGA showed no trace of rust
while the hot-dip galvanised buoy was severely corroded in several places.

Left: Buoy treated with ZINGA + topcoat

Right: Buoy treated with HDG + topcoat



ZINGA ON REBARS

ASTM B117 / ISO 9227 (SALT SPRAY TESTING) - SAI / JU / AUPTT*

Steel Authority of India (2006):
A comparison was made between uncoated steel rebars, fusion bonded epoxy coated rebars (FBEC), hot-dip galvanised rebars (HDG) and zinganised rebars (ZINGA). The corrosion rate per year was measured after immersion and salt spray. This test demonstrated several advantages of ZINGA: the greater degree of galvanic protection, the lower sacrificial zinc consumption due to the dispersion of zinc dust in the binder and the additional barrier protection created by the binder.
ZINGA > FBEC > HDG > Uncoated

Jadavpur University (2006):
A comparison was made between uncoated steel (Mild steel and Stainless steel) rebars, fusion bonded epoxy coated rebars (FBEC), hot-dip galvanised rebars (HDG) and zinganised rebars (ZINGA). The salt spray test pointed out that the zinganised rebars have a corrosion resistance that is about 2 times higher than that of hot-dip galvanised rebars. ZINGA is also least susceptible for stress corrosion cracking.
in NACE solution: ZINGA > HDG > FBEC > Stainless steel > Mild steel

Amirkabir University Poly Technic Tehran (2008):
The zinganised rebars passed the 500 hours salt spray test without formation of rust, peeling or blistering, not even in places where the coating was mechanically damaged. The rebars that were not zinganised were heavily corroded.





ISO 1519 (BEND TEST) - COT

ISO 1519: Paints and varnishes -- Bend test (cylindrical mandrel)

ZINGA has been applied at a layer thickness of 60 µm DFT on test panels and bent by a mandrel tester at 23°C and 50% RV. The diameter of the mandrels are 32 mm, 25 mm, 20 mm, 16 mm, 13 mm, 12 mm, 10 mm, 8 mm, 6 mm, 5 mm, 4 mm, 3 mm and 2 mm.
Immediately after bending, the coating has been examined under good illumination with normal corrected vision.

ZINGA showed no cracks when bending on a cylindrical mandrel with a diameter of 12 mm.



RILEM / CEB / FIP RC6 (PULL OUT TEST) - UGENT

RILEM/CEM/FIP Recommendation RC6-1978: Technical Recommendations for the Testing and Use of Construction Materials: Bond test reinforcing steel - 2. Pull-out test

Three rebars with enhanced adhercnce L = 1000 mm; ø =18 mm were tested.

- One rebar is embedded in concrete in the uncoated condition.
- Two rebars were first coated with a ZINGA coating of 25 µm over a length of 500 mm and subsequenty. after 72 hours of drying time, embedded in concrete.

The rebars were embedded in the center of concrete cubes and a plastic tube is slipped over the rebar in such a way that only 90 mm of the rebar is in contact with the concrete.
After 28 days cure, the pull-out test was performed.

An average adhesion force for ZINGA on rebars of 17.03 N/mm was found. This was comparable to the uncoated rebars (18.90 N/mm).
It was concluded by Prof. Dr. Eng. Defrancq that the adhesion to concrete of rebars coated with ZINGA is not advesely affected compared to the adhesion of non coated rebars.

CLEAVE ADHESION TEST - B-HOLDING*

A custom test was designed to test the adhesion of (zinganised) rebars to the concrete. A rebar coated with ZINGA, an untreated and a sandblasted rebar were imbedded in concrete.
The rebars were aged using SO_2 (Kesternich).

The concrete was cleaved, in order to set free the steel reinforcement.

Conclusion:
It is clearly more difficult to cleave the rebar bloc containing the steel rod protected with ZINGA. The adherence of the concrete to the Zinganised rod is better. The actual cleavage happens in the concrete (in contrast to the other two rebars, which cleaved neatly between steel and concrete), which indicates a strong adherence.





* B-Holding (Belgium)

(NON) TOXICITY OF ZINGA

AS/NZS 4020 (CONTACT WITH DRINKING WATER TEST) - AWQC*

AS/NZS 4020 (2005): Testing of products for use in contact with drinking water

ZINGA was put through extensive testing by the Australian Water Quality Centre.
The water in contact with ZINGA was tested on taste (1000 mm^2/L) and appearance (15000 mm^2/L), on growth of aquatic micro-organisms (6300 mm^2/L), cytotoxic and mutagenic activity (15000 mm^2/L) and an analysis of a metal extraction (15000 mm^2/L) was performed.

The results demonstrate compliance to AS/NZS 4020 for ZINGA.

BS 6920 (CONTACT WITH DRINKING WATER TEST) - WRAS*

BS 6920: Suitability of non-metallic products for use in contact with water intended for human consumption with regard to their effect on the quality of the water.

Even though ZINGA is a metallic coating, it was tested according to the standard BS 6920 to determine whether or not the quality of potable water is affected when it is in contact with a ZINGA layer.

The water was analysed on taste, appearance, growth of micro organisms, extraction of harmful substances and extraction of metals. The obtained results complied with the requirements and ZINGA was found suitable for contact with potable water.

Since its review in 2008, ZINGA could no longer be tested according this standard excluding al metallic coatings.

ZINGA RELIQUIFICATION

MICROSCOPIC ANALYSIS - UGENT


A custom test was designed to demonstrate that a newly applied ZINGA layer makes the former layer liquid again so that both layers blend together to one single homogeneous layer. The new layer recharges the old one.

A thin copper film layer was applied on top of ZINGA and photographed. Afterwards, a second layer of ZINGA was applied an the layer was photographed again. The same procedure was repeated with a zinc rich coating.

The first picture shows dispersion of the copper layer through the blended ZINGA layer, while the second depicts two separated layers with the copper layer in between.

The ZINGA film galvanising system is very easy to maintain and to recharge: there is no need for gritblasting, contrary to the surface preparation that is required when a traditional paint has been used.


Copper particles on top of ZINGA


Copper particles blend in two layers of ZINGA


Copper particles in between the two layers of epoxy paint

* AWQC - Australian Water Quality Centre (Australia) / WRAS - Water Regulations Advisory Scheme (UK)

MACROSCOPIC ANALYSIS - STANGERS

Dried "caked" ZINGA was reliquidised using new ZINGA on different plates, brushes and different times of drying.
It was found that "ZINGA is easy to apply by brush and resoftens caked ZINGA or dry ZINGA films as claimed by the manufacturer. This property enables ZINGA to be built up into thick composite layers avoiding the discrete films achieved with conventional coatings."

End conclusion: "It is evident that the product has special properties which place it, as far as we know, into a unique category."

SURFACE SPREAD OF FLAMES OF ZINGA

EN 13501-1 (FIRE TEST) - EFECTIS

EN 13501-1 (2007) + A1 (2009): Fire classification of construction products and building elements - Part 1: Classification using data from reaction to fire tests

Determination of the ignitability properties of the product, by direct small flame impingement according to EN ISO 11925-2:2010, with the objective to obtain the reaction to fire classification according to EN 13501-1:2007+A1:2009.

Determination of the reaction to fire properties of the product, when exposed to the termal attack by a single burning item according to EN 13823:201, with the objective to obtain the reaction to fire classification according to EN 13501-1:2007+A1:2009.

A total of twelve single ignitability tests were carried out according to EN ISO 11925-2.

A total of three single burning item tests were carried out according to EN 13823.

ZINGA 2 x 90 µm DFT Reaction to fire classification: **B - s1, d0**



BS 476-6 (FIRE TEST) - SGS YARSLEY TECHNICAL SERVICES

BS 476-6: Fire Tests on Building materials and structures – Method of test for fire propagation for products

This Part of BS 476 specifies a method of test, the result being expressed as a fire propagation index, that provides a comparative measure of the contribution to the growth of fire made by an essentially flat material, composite or assembly. It is primarily intended for the assessment of the performance of internal wall and ceiling linings.

The results of the test according to the BS 476: part 6 show that ZINGA has a class 0 surface. ZINGA did not ignite during exposure to heating.

FRICTION COEFFICIENT OF ZINGA

GB 50017-2003 & GB 50205-2001 (ANTI-SLIP COEFFICIENT) - CNCSQSTC*

GB 50017-2003 Code for design of steel structures
GB 50205-2001 Code for Acceptance of Construction Quality of Steel Structures

In Octobre 2005, ZINGA coated plates have been tested according GB 50017 and GB 50205 to assess the slip friction coefficient (μ) of high strength bolts adjoining steel sections.

The results demonstrate that ZINGA coated surfaces of high strenght bolts have increased friction (compared to bare steel or galvanised steel) with results of μ between 0.5 and 0.7. This is beneficial for construction.

ASTM A325 & A490 (ANTI-SLIP COEFFICIENT) - KTA TATOR*

ASTM A490: Standard Specification for Structural Bolts, Alloy Steel, Heat Treated, 150 ksi Minimum Tensile Strength
ASTM A325: Standard Specification for Structural Bolts, Steel, Heat Treated, 120/105 ksi Minimum Tensile Strength

Plates coated with 100 μm DFT of ZINGA, were loaded onto a horizontal rod, based on contact surfaces having similar coating thickness. A clamping force of 49 kips (= 218 kN) was applied to the test assembly, then a compressive load was applied to the machined edge of the middle plate at a rate no-to-exceed 25 kips/minute, to induce a slip. The slip load for each test assembly is divided by two times the clamping force to obtain the slip coefficient.


ZINGA exhibited a slip coefficient of 0.52 and passed the 1,000 hour Creep Deformation test. ZINGA is therefore certified class B.

WELDING OF ZINGA

WELDING TEST - UGENT

A set of 3 x 2 plates, covered with a layer of ZINGA, the thickness of which was respectively 15 μm DFT, 40 μm DFT and 60 μm DFT. After a polymerisation period of seven days the two plates covered with the same coating thickness were welded together by hand.

None of the 3 specimens shows any deficiency, neither in the welding seams nor in the steel itself.





WELDING TRIALS - TATA STEEL*

Before their use of ZINGA on rail tracks, TATA Steel investigated not only the performance of the coating, but also its weldability.
On trials, they performed weld trials with ZINGA coated tracks and found that the process was not negatively affected by the coating. No localised melting of the zinc based coating had occurred and there was no evidence of die burns or pick up in either the rails or the copper dies.

The four foot length was subsequently bend tested and despite the apparent slippage broke at 1430 kN. This comfortably passed the Network Rail specification minimum of 1220 kN. The grab marks induced by the compressional strength of 1.5 tons, required to hold the rail-track ends together during the welding operation illustrate how ZINGA was crushed into the metal during this phase.

* China National Construction Steel Quality Supervision and Test Center (China) / KTA Tator (USA) / TATA Steel (World wide)

COT bv
Independent advice, research and management for construction and industry



Consultancy
Laboratory

Jan Tademaweg 40
2031 CV Haarlem
P.O. Box 2113
2002 CC Haarlem
The Netherlands
T +31 23-5319544
F +31 23-5277229
E info@cot-nl.com
I www.cot-nl.com

REPORT

Testing of Zingametall system
Zinga 2x 60 micrometer
according to ISO 12944-6 (2018) C5 Very High

Haarlem, March 26th, 2018

Client	:	Zingametall bvba Industriepark Rozenstraat 4 9810 EKE Belgium Contact person: Mr. J. Serck
Project number	:	20120445
Report number	:	LAB18-0119-REP

Copy Right COT bv. This report contains 5 numbered pages and is property of COT bv (Netherlands). No part of this report may be copied, distributed, inserted in any text document, or reproduced in any other way or published, without written permission of COT bv (Netherlands). This report is not transferable to any person or body, serves only to take cognisable and gives in no way the rights on this report , neither can lay a claim to any in this report discussed product or method. Use of information from this report is not permitted without written permission of COT bv. When not agreed in the by COT bv provided order confirmation, our Rules of Service are applicable.

CONTENTS

1 INTRODUCTION 3
1.1 Order 3
1.2 Samples 3

2 PAINT APPLICATION AND CURING 3

3 PERFORMANCE TESTS 4
3.1 Cyclic test 4
3.2 Adhesion test 4

4 REQUIREMENTS 4
4.1 Cyclic test 4

5 RESULTS 5
5.1 Original adhesion value 5
5.2 Cyclic Test 5

6 CONCLUSION 5

1 INTRODUCTION

1.1 Order

By order of Zingametall bvba in Eke, Belgium, The Centrum voor Onderzoek en Technisch Advies (COT bv) has tested the system Zinga 2 X 60 µm according to ISO 12944-6 (2018) C5 VH. The order has been given in the letter dated 18-08-2006 with reference Testen/Algemeen/ COT/2/1-SD.

1.2 Samples

COT sample number	Sample	Batch number
22-08-06/0667	Test panels, applied with the system: Zinga, 2x 60 µm test panels, size: 150 x 75 x 5 mm 150 x 300 x 5 mm	--

2 PAINT APPLICATION AND CURING

The coating system was applied on the test panels by Zingametall.

Dry film thickness Zinga: 2x 60 µm

After curing the dry film thickness of the paint system has been measured on each panel, after which the tests have been started.

3 PERFORMANCE TESTS

3.1 Cyclic test

The fully cured coating system has been mechanically scribed horizontal down to bare metal. The scratch line is 2 mm wide and 50 mm long. The system has been exposed to the following cycle according to ISO 12944-6 (2018) C5 VH:

72 hours	UV-A 340 nm weatherometer in accordance with ISO 16474-3 (4 hours UV-light at 60 °C / 4 hours condensation at 50 °C)
72 hours	Salt Spray Test, according to ISO 9227 with synthetic seawater in accordance with ASTM D 1141
24 hours	Exposure to low temperature (-20 °C).

The total exposure time is 2688 hours.

3.2 Adhesion test

The adhesion before and after the cyclic test has been determined by a pneumatic adhesion tester in accordance with ISO 4624. The coating surface and the dolly have been sanded lightly and a epoxy adhesive has been applied. After curing of the adhesive and prior to testing, the coating has been scratched around the dolly down to the bare metal. Three trials have been done and the average value has been reported.

4 REQUIREMENTS

4.1 Cyclic test

After exposure to the specified time, the test panels shall comply with the following requirements:

Method		**Requirements**
--	Corrosion creep from scribe*	< 3.0 millimetres
ISO 4628-2	Blistering	0
ISO 4628-3	Rusting	0
ISO 4628-4	Cracking	0
ISO 4628-5	Flaking	0
ISO 4624	Adhesion	min. 2.5 MPa for each measurement

* The corrosion creep is calculated from the equation: M=(C-W)/2, where
M = corrosion creep
C = average of the nine measurements
W = the original width of the scribe.

5 RESULTS

5.1 Original adhesion value

The original Adhesion value is 4.7 ± 0.1 MPa.

5.2 Cyclic Test

Exposure Time: 2688 hours*

	Panel 1	Panel 2	Panel 3
Dry film thickness (µm)	154 ± 7	138 ± 9	163 ± 11
Corrosion creep from scribe (mm)	0	0	0
ISO 4628-2 Blistering	0	0	0
ISO 4628-3 Rusting	0	0	0
ISO 4628-4 Cracking	0	0	0
ISO 4628-5 Flaking	0	0	0
ISO 4624 Adhesion (MPa)	7.5 ± 0.0	6.6 ± 0.6	7.2 ± 0.0

*) results have been inferred of 4200 h testing.

6 CONCLUSION

The system Zinga, dry film thickness 60/60 µm, meets the evaluated requirements of ISO 12944-6 (2018) C5 VH.

CENTRUM VOOR ONDERZOEK
EN TECHNISCH ADVIES (COT)

Dr. B.P. Alblas
Manager Laboratory

J.R.S. Brakenhoff
Technical Manager Laboratory

COT bv
Independent advice, research and management for construction and industry



Consultancy
Laboratory

Jan Tademaweg 40
2031 CV Haarlem
P.O. Box 2113
2002 CC Haarlem
The Netherlands
T +31 23-5319544
F +31 23-5277229
E info@cot-nl.com
I www.cot-nl.com

REPORT

Testing of Zingametall system
Zinga 2x 60 micrometer
according to ISO 12944-9 (2018)

Haarlem, April 24th, 2018

Client	:	Zingametall bvba Industriepark Rozenstraat 4 9810 EKE Belgium Contact person: Mr. J. Serck
Project number	:	20120445
Report number	:	LAB18-0160-REP

Copy Right COT bv. This report contains 5 numbered pages and is property of COT bv (Netherlands). No part of this report may be copied, distributed, inserted in any text document, or reproduced in any other way or published, without written permission of COT bv (Netherlands). This report is not transferable to any person or body, serves only to take cognisable and gives in no way the rights on this report , neither can lay a claim to any in this report discussed product or method. Use of information from this report is not permitted without written permission of COT bv. When not agreed in the by COT bv provided order confirmation, our Rules of Service are applicable.

CONTENTS

1 INTRODUCTION 3
1.1 Order 3
1.2 Samples 3

2 PAINT APPLICATION AND CURING 3

3 PERFORMANCE TESTS 4
3.1 Cyclic test 4
3.2 Adhesion test 4

4 REQUIREMENTS 4
4.1 Cyclic test 4

5 RESULTS 5
5.1 Original adhesion value 5
5.2 Cyclic Test 5

6 CONCLUSION 5

1 INTRODUCTION

1.1 Order

By order of Zingametall bvba in Eke, Belgium, The Centrum voor Onderzoek en Technisch Advies (COT bv) has tested the system Zinga 2 X 60 µm according to ISO 12944-9 (2018) CX.
The order has been given in the letter dated 18-08-2006 with reference Testen/Algemeen/ COT/2/1-SD.

1.2 Samples

COT sample number	Sample	Batch number
22-08-06/0667	Test panels, applied with the system: Zinga, 2x 60 µm test panels, size: 150 x 75 x 5 mm 150 x 300 x 5 mm	--

2 PAINT APPLICATION AND CURING

The coating system was applied on the test panels by Zingametall.

Dry film thickness Zinga: 2x 60 µm

After curing the dry film thickness of the paint system has been measured on each panel, after which the tests have been started.

3 PERFORMANCE TESTS

3.1 Cyclic test

The fully cured coating system has been mechanically scribed horizontal down to bare metal. The scratch line is 2 mm wide and 50 mm long. The system has been exposed to the following cycle according to ISO 12944-9 (2018) CX:

72 hours	UV-A 340 nm weatherometer in accordance with ISO 16474-3 (4 hours UV-light at 60 °C / 4 hours condensation at 50 °C)
72 hours	Salt Spray Test, according to ISO 9227 with synthetic seawater in accordance with ASTM D 1141
24 hours	Exposure to low temperature (-20 °C).

The total exposure time is 4200 hours.

3.2 Adhesion test

The adhesion before and after the cyclic test has been determined by a pneumatic adhesion tester in accordance with ISO 4624. The coating surface and the dolly have been sanded lightly and a epoxy adhesive has been applied. After curing of the adhesive and prior to testing, the coating has been scratched around the dolly down to the bare metal. Three trials have been done and the average value has been reported.

4 REQUIREMENTS

4.1 Cyclic test

After exposure to the specified time, the test panels shall comply with the following requirements:

Method		**Requirements**
--	Corrosion creep from scribe*	< 3.0 millimetres
ISO 4628-2	Blistering	0
ISO 4628-3	Rusting	0
ISO 4628-4	Cracking	0
ISO 4628-5	Flaking	0
ISO 4624	Adhesion	min. 5.0 MPa, max. 50% reduction from original value

* The corrosion creep is calculated from the equation: M=(C-W)/2, where
M = corrosion creep
C = average of the nine measurements
W = the original width of the scribe.

5 RESULTS

5.1 Original adhesion value

The original Adhesion value is 4.7 ± 0.1 MPa.

5.2 Cyclic Test

Exposure Time: 4200 hours

	Panel 1	Panel 2	Panel 3
Dry film thickness (µm)	154 ± 7	138 ± 9	163 ± 11
Corrosion creep from scribe (mm)	0	0	0
ISO 4628-2 Blistering	0	0	0
ISO 4628-3 Rusting	0	0	0
ISO 4628-4 Cracking	0	0	0
ISO 4628-5 Flaking	0	0	0
ISO 4624 Adhesion (MPa)	7.5 ± 0.0	6.6 ± 0.6	7.2 ± 0.0

6 CONCLUSION

The system Zinga, dry film thickness 60/60 µm, meets the evaluated requirements of ISO 12944-9 (2018) CX.

CENTRUM VOOR ONDERZOEK
EN TECHNISCH ADVIES (COT)

Dr. B.P. Alblas
Manager Laboratory

J.R.S. Brakenhoff
Technical Manager Laboratory